

Subject: Front Sub-Reefer and Dry Vans

Utility Trailer Manufacturing Company does **not** recommend any type of front sub modification, kingpin replacement, or cutting out the top and / or bottom plate of the box beam.

Worn, damaged and improperly located kingpins require removal and replacement of the **entire** front sub assembly (approach plate and H-Beam assembly w/king pin).

If you have any questions, please call the Field Service Department at 1-800-423-6591.

Field Service Department
Utility Trailer Manufacturing Company