



## SERVICE BULLETIN NO. SB-08-069

Issue Date: 04/12/2004

|                 |  |
|-----------------|--|
| <b>SUBJECT:</b> | <b>Hendrickson Tiremaax Tire Inflation System Manual</b> |
|-----------------|--|

Hendrickson has released the TIREMAAX Tire Inflation System manual, L818. This manual covers installation, service and troubleshooting procedures.

Click on the link below to view the manual.

[http://www.hendrickson-intl.com/pdfs/trailer\\_PDFs/L818.pdf](http://www.hendrickson-intl.com/pdfs/trailer_PDFs/L818.pdf)

Any questions regarding the manual should be directed to Hendrickson, USA at 866-743-3247 or Canada at 800-668-5360.

Any questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

**Field Service Department**  
**UTILITY TRAILER MANUFACTURING COMPANY**