

SERVICE BULLETIN NO. SB-07-010, "A" REVISION
(supersedes previous issue of SB-07-010 June 2006)

JUNE 28, 2006

**SUBJECT: PRE-1998 TRAILERS - UTM RECOMMENDATION WHEN
REPAIRING OR REPLACING REAR BUMPERS**

On Utility trailers manufactured prior to January 1998 with a UTM design rear bumper and which are in need of repair due to damage, the bumper on such a trailer should be returned to its original (OEM) state at the time of manufacture. Replacement parts are available through Utility's After-market Division.

IMPORTANT: Do not use the Holland (Binkley) bumper on any Utility trailers. Refer to Utility Service Bulletin No. SB-07-009 for details.

If a customer requests an upgrade to our current design, at his expense, contact the Field Service Department.

Any further questions may be directed to the Field Service Department at 800-423-6591.

**Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY**

SB-07-010