

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



PU-08-001

Issue date: June 01, 2015

Product Update: Hendrickson Aftermarket Height Control Valve

Please read the attached product update from Hendrickson. If you have any questions regarding the information indicated, please contact your Hendrickson service representative at 330.489.0479

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY

Utility hasn't independently evaluated the information contained in the attached Aftermarket Height Control Valve Product Update from Hendrickson; it is making the product update available as a convenience and for information purposes. You are encouraged to contact Hendrickson at (330-489-0479) if you have any questions concerning the content of the document, or how these issues affect trailers you are servicing.



May 29, 2015

Attention:

**Engineering Managers
Purchasing Managers
Production Managers
Quality Managers
Service Managers
Parts Managers**

(Please copy to other concerned departments)

Please see attached document!

Product Update:

Aftermarket Height Control Valves


HENDRICKSON® PRODUCT UPDATE

Aftermarket Height Control Valves

LIT NO: P56019

DATE: May 2015

Hendrickson Trailer Commercial Vehicle Systems announces a change to aftermarket Height Control Valves (HCVs). Beginning mid-June 2015, the HCV control arms will be extended in length by one inch and modified to include a third mounting hole. To determine the proper mounting hole for a specific suspension, refer to the chart below.



The function of the height control valve is unaffected by these modifications. This control arm change applies to Hendrickson aftermarket replacement HCVs only and current replacement part numbers are unchanged. Therefore, VS-227 and VS-227-BK (Standard HCV), and VS-228 (Integral Dump HCV) aftermarket kits will include the new HCVs. Components are fully reverse compatible. Please note, these replacement valves are designed to work on all Hendrickson suspension models **excluding** VANTRAAX® ULTRA-K®.

As always, Hendrickson is committed to providing world class products and exceptional customer service. Please contact your Hendrickson Sales Representative or call 1-866-RIDEAIR (743-3247) if you have questions regarding this change.

SUSPENSION MODEL *	LOWER HCV BRACKET LOCATION	HOLE
INTRAAX® - AANT, AAT, AANL, AANLS	Attached to brake chamber bracket	P1
VANTRAAX® - HKANT, HKAT, HKARL		
INTRAAX-SP - AAZNT		
HT™ Series - All non "US" models		
HK™ Series - All		
HS Series - All		
INTRAAX - AAL, AAEDL, AAEDT	Attached to air spring pedestal	P2
VANTRAAX - HKAL		
INTRAAX-SP-AAZL		
HT Series - HT250US, HT300US		
VANTRAAX - HKANT, HKAT		P3

* For VANTRAAX ULTRA-K, use VS-33704-3 (HCV) and VS-33705-3 (HCVD) aftermarket replacement valves.

Call your trailer dealer or Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.

HENDRICKSON

www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601