

SERVICE BULLETIN NO. SB-08-062

Issue Date: 1/23/2004

SUBJECT: ArvinMeritor Service Manual Revision TP-96175 (Revised 08-03)

A revised edition of the ArvinMeritor Service Manual TP-96175 (Revised 08-03) has been released. Section 5: **Inspection intervals** and **Inspect the Unitized Wheel End** categories were amended. Note: Inspect the hub for smooth rotation, movement, seal leaks and bearing end play at every 100,000 miles (161,000 km) or 12 months, whichever comes first.

The Service Manual can be obtained from the WEB at the link below or by contacting ArvinMeritor's Customer Service Center at 800-535-5560.

www.arvinmeritor.com/tech_library/documents/tp96175.pdf

Any questions regarding the ArvinMeritor Service Manual revision should be directed to the ArvinMeritor Customer Service Center at 800-535-5560.

Any questions regarding this service bulletin should be directed to the Utility Trailer Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY