



SERVICE BULLETIN NO. SB-05-006

Issue date: September 30, 2010

**SUBJECT: JOST INTERNATIONAL – Technical Bulletin:
Winter Hard Cranking Landing Gear**

JOST INTERNATIONAL has now made available a Technical Bulletin for trouble shooting landing gear that is hard to crank in low temperature conditions which is now accessible on their web site.

<http://www.jostinternational.com/Winter Hard Cranking Landing Gear>

Any questions regarding the content of their document may be directed to:

JOST at (616) 846-7700

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department

UTILITY TRAILER MANUFACTURING COMPANY