

SERVICE BULLETIN NO. SB-08-061

Issue Date: 10/26/2004

SUBJECT: ArvinMeritor MTIS Inspection Intervals

Please note that the Arvin Meritor Tire Inflation System (MTIS) rotary union (Through-Tee) is a wearable item and as such should be inspected as per recommendation in MTIS Maintenance Manual #14P. On a standard-duty on highway trailer the MTIS inspection interval is every 100,000 miles or 12 months, whichever comes first. The through-tee can be replaced without removing the hubcaps or disturbing the wheel bearings.

Below is the link to the ArvinMeritor MTIS Maintenance Manual. The trouble-shooting guide is on page 31.

http://www.arvinmeritor.com/tech_library/documents/mm14p_.pdf

All ArvinMeritor claims are to be filed through ArvinMeritor's Ontrac Customer Support Group at 800-866-7221.

Any questions regarding the inspection intervals or the MTIS Maintenance Manual should be directed to Arvin Meritor's Ontrac support group at 800-866-7221.

Any questions regarding this service bulletin should be directed to the Utility Trailer Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY