

SERVICE BULLETIN NO. SB-08-064

Issue Date: 2/05/2004

SUBJECT:	ConMet PreSet Hub Assembly, Periodic Inspection and Preventative Maintenance.
-----------------	--

Warranty coverage for ConMet Preset hubs requires an annual inspection as detailed in their "PreSet Service Manual" 10005642.

The annual inspection requires a visual inspection of the Preset Hub Assembly be conducted every 12 months or 100,000 miles, whichever comes first. In addition ConMet requires Preset hub service at 500,000-mile intervals or 5-years, whichever comes first. These inspection requirements apply regardless of wheel end type and usage.

ConMet Preset Hub Service Manual 10005642

http://www.conmet.com/pdfs/preset_serv_manual_revb.pdf

Failure to conduct the required inspections will void the published warranty. Any questions regarding this policy should be directed to ConMet at 800-547-9473.

Any questions regarding this service bulletin should be directed to the Utility Trailer Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY