

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



SB-08-122

Issue date: January 28, 2010

Revised date: June 12, 2013

ConMet PreSet Hub Assemblies Upgrade in Oil Seals

Please [click this link](#) to be directed to an announcement from ConMet detailing the products included in the PreSet and PreSet Plus Hub Assemblies.

Effective 05/06/2013 – ConMet has upgraded the standard oil seal to a National oil seal (new part numbers will not be assigned). The CR Scottseal Plus XL seal will still be available upon request. The Outrunner and Stemco Endeavor oil seals will no longer be available.

The new National Hub-Mounted seal part #'s are:

TN: 380025

TP: 380065



File any leaking oil seals with Federal Mogul (National) per Service Bulletin #[SB-08-152](#).

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY

Utility hasn't independently evaluated the information contained in the attached technical bulletin; it is making the bulletin available as a convenience and for information purposes. You are encouraged to contact Hendrickson at (866) 743-3247 if you have any questions concerning the content of the document, or how these issues affect trailers you are servicing.