



SERVICE BULLETIN NO. SB-08-134

Issue date: November 12, 2010

**SUBJECT: Hendrickson Product Update –
Wheel Seal Change on Non-Preset Air Brake Specifications**

See the attached Hendrickson Product Update for information regarding the wheel seal change on non-preset air disc brake specifications.

*Included LIT NO: P76001

Any questions regarding the Hendrickson's Product Update should be directed to Hendrickson at 866-743-3247.

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY




WHEEL SEAL CHANGE ON NON-PRESET AIR DISC BRAKE SPECIFICATIONS

LIT NO: P76001

DATE: November 2010

Hendrickson Trailer Suspension Systems is pleased to announce a wheel seal upgrade on ADB (Air Disc Brake) specifications. Effective immediately, the premium National Oil "Gold Seal" from Federal-Mogul will be the standard wheel seal in all ADB specifications (excluding ConMet PreSet ADB hubs*) shipped on Hendrickson INTRAAX®, VANTRAAX® and most trailer axle models, including TRLAXLE™. This ADB wheel seal upgrade is compatible with all three ADB systems available from Hendrickson: Knorr/Bendix ADB22X, Haldex DB22LT and WABCO PAN22.

The premium "Gold Seal" incorporates a PTFE (Teflon) main sealing lip that provides superior heat resistance making it a perfect match for ADB wheel-end applications, as ADBs can operate at higher temperatures than drum brakes, particularly during frequent brake applications. As a result, all new ADB orders for Hendrickson INTRAAX, VANTRAAX and TRLAXLE model numbers will be configured with the "Gold Seal". Existing model numbers will be changed to incorporate the "Gold Seal".



This wheel seal upgrade is another example of Hendrickson's commitment to continuous improvement to enhance the value and lifespan of your equipment. For additional information on the "Gold Seal", contact Hendrickson or refer to these web site addresses:

http://www.hendrickson-intl.com/pdfs/FM/NWEC Gold Seal Trade Ad_final_1027.pdf
http://www.hendrickson-intl.com/pdfs/FM/37_38Series%20Flyer_081707.pdf

If you have any questions, please notify your trailer account manager or call 1-866-RIDE-AIR (866-743-3247) and ask to speak with your customer or technical service representative.

* ConMet PreSet ADB hubs come equipped with ConMet-approved wheel seals pre-installed in their assembly.

www.hendrickson-intl.com



Trailer Suspension Systems
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
Fax 905.789.1033

Trailer Suspension Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA

866.RIDEAIR (743.3247)
330.489.0045
Fax 800.696.4416

Hendrickson Mexicana
Av. Industria Automotriz #200
Parque Industrial Siva Aeropuerto
Apodaca, N.L., México C.P. 66600
+52 (81) 8288.1300
Fax +52 (81) 8288.1301