

SERVICE BULLETIN

UTILITY TRAILER MANUFACTURING CO.



SB-20-005

Issue date: April 12, 2013

Michelin: Usual Suspects for Tire Wear Pattern

Refer to the following link regarding Irregular Trailer Tire Conditions.

[Michelin: Usual Suspects for Irregular Trailer Tire Conditions](#)

Any other questions regarding this service bulletin should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY

Utility hasn't independently evaluated the information contained in the attached technical bulletin; it is making the bulletin available as a convenience and for information purposes. You are encouraged to contact Michelin at (866) 866-6605 if you have any questions concerning the content of the document, or how these issues affect trailers you are servicing.

Page 1 of 1